

The Commonwealth of Massachusetts Executive Office of Environmental Affairs Department of Environmental Protection Bureau of Waste Site Cleanup

Daniel S. Greenbaum Commissioner

One Winter Street, Boston, Massachusetts 02108

James C. Golman Assistant Commissioner

Superfund Records Center SITE:WINKESTER JNOUSTRIE

BREAK: 1.02

OTHER: 621200

DU 00

MEMORANDUM

To:

Helen Waldorf, Branch Chief, BWSC

Madeline Snow, Division Director, RR

From:

Winifred Donnelly Regional Planner

Date:

June 30, 1990

Subject:

MSCA Preliminary Assessment Report

Winchester Industries 230 Bodwell Street Avon, Massachusetts

Attached, please find the Preliminary Assessment (PA) Package for Winchester Industries. This package is to be submitted to the EPA in order to fulfill our commitment to the MSCA grant. Included in this package is EPA form 2070-12, and a narrative summary that includes the site description, facility activity and history, nearby water bodies summary, and the recommendation.

It is recommended that this site be given medium priority status. Although sampling revealed BDL, it is difficult to ascertain groundwater flow direction. The proximity of a possible future water supply source leaves no room for doubts about keeping this water body in a pristine condition.



SEMS DocID

627200

INTRODUCTION

This Preliminary Assessment is being performed in compliance with the mandates of the Multi Site Cooperative Agreement, for the benefit of the Environmental Protection Agency.

DESCRIPTION AND HISTORY

The site Winchester Industries, is located at 230 Bodwell Street, Avon, Massachusetts (DEP site number 4-0634). The operations of Winchester Industries have since moved to 491 Main Street in Avon. Efforts to ascertain who the current tenant/owner of the property were curtailed by the town of Avon's assessor's office.

The property is approximately 2 acres in size. It contained two buildings. Building A is a one story structure, approximately 16,000 square feet in size. This structure housed the manufacturing and assembling facility. Building B is the same size as building A. The front portion housed the offices. The rear section was divided between warehouse space for Winchester Industries, and a hardware supplier, the Jaques Company. There is a grassy area between these two buildings. In front of the buildings lie landscaped lawns.

There are no underground fuel storage tanks located on site.

To the rear of the buildings is a fenced enclosed, concrete deck. On the deck is a stainless steel container used for the protection and storage of used lacquer. This deck is also used for the storage of non-hazardous unfinished materials.

The topography slopes gently to the west, towards the rear of the site. The rear of the property is within the 100-500 year flood plain of Beaver Creek.

The site lies in a commercial area of the town. The abutting property to the north is occupied by Thorsen/ Confab, a computer hardware company. To the south is Grossman Cap Company. The lot behind the site to the west is an undeveloped vacant parcel with a small hill comprised of bedrock boulders. Directly across Bodwell Street to the east, are the truck storage and maintenance facilities of Parker Transportation.

FACILITY ACTIVITY/HISTORY

The site was undeveloped prior to 1972, when the owner of Winchester Industries, Mr. Peter Runton purchased the property from Mr. George Hoag. Construction of building A started in 1972, and construction of building B began in 1979.

The manufacturing process uses metals reported as brass, aluminum and steel. The bright dip method was used to clean the metals. The waste water from this process was treated to remove residual chromium and copper. Acids used for etching were chromic acid and phosphoric acid. Every four to five months, two 55 gallon drums of the phosphoric were used. Sulfuric acid had been used in the past. These materials were stored in the northwest corner of building A. Other hazardous materials used include paints and lacquers, which were stored in a flame retardant locker.

Each week, a degreasing process used 70 gallons of trichloroethene. A fume recovery vent for degreasing was located near the middle of the building. Waste solvent (TCE) was transported off site weekly by Clean Harbors Inc.

No signs of visible contamination was evident on the property grounds, except for minor surficial staining of the bituminous concrete pavement. The staining appears to be caused by local traffic within the parking lot, and not the result of unauthorized releases.

A Notice of Violation was issued by the Department of Environmental Protection, RCRA Section, on May 15, 1985, that pertained to the storage and documentation of hazardous wastes and materials. On September 25, 1987, the agency sent a letter stating that the problem had been satisfactorily addressed. Winchester Industries applied for a change of status from a Large Quantity Generator, to a Small Quantity Generator on 3/8/89. The reason for the change is a new system which was put in place when the operation moved to Main Street. The operator of the current location is Gary Goodine.

No reference of contamination on site was found at the Avon Board of Health or Fire Department.

On 2/3/88, Peter Flink of Kurz Associates made a site visit for the purpose of an interior building inspection. A sweet solvent odor was noted at the time, but was relegated as emitting from an air vent on a neighboring building.

During the same month, observation wells were dug, and groundwater samples were taken. The septic system was also sampled. Chlorinated hydrocarbons were detected in the water samples. Trichlorethene levels were highest in the primary septic holding tank. The solvent must have been disposed of into the system at some time. Traces of toluene, ethylbenzene and xylene were found in the soil.

During June and July of 1988, split spoon, and water samples were taken. Chlorinated solvents and cadmium were found on the site. However, additional sampling revealed levels were BDL.

WATER SUPPLIES

The nearest water supply source, a supply well for the town of Avon, is situated over a mile away. It lies to the east of the site. Within three miles, three wells for the town of Holbrook are situated.

Also, within two miles, lies the Brockton Reservoir. Although not a water supply at the present time, there are discussions on the potential use of this water body for the City of Brockton. The City of Brockton expects the reservoir to be on line in the Spring of 1991.

Beaver Brook flows into the Brockton Reservoir. The drainage easement on site drains into Beaver Brook.

RECOMMENDATION

Due to the possibility of Brockton Reservoir being used as a drinking water source, it is recommended that this site be listed for a medium Screening Site Inspection (SSI). Although follow up sampling revealed BDL, the samples were sparse. Groundwater samples were only taken from one well (MW5). It was stated in 8/88, that ground water radiated in all directions from this particular well. It was also stated that groundwater flow is hard to pinpoint because the system is so complex. Therefore MW5 was a poor choice from which to take samples.

Local geological conditions created a complex system for groundwater flow. Ground water in the vicinity of the leaching fields is estimated to radiate in all directions, with a regional flow southward. This complex system calls for additional monitoring.

SEPA

EPA FORM 2070-12 (7-81)

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT PART 1 - BITE INFORMATION AND ASSESSMENT

'L IDENTIFICATION				
DISTATE	02 BITE NUMBER			
MAD	002578417			

IL SITE NAME AND LOCATION	Tarianos		no speciatio	LOCATION IDEN	ന്നല്ല		
OT SITE HAME (Lague, description, or description acres of step)	NAME (Layer, common, or description name of ado)					•	
Winchester Industries		230 Bodwell St.			YINA CONG		
03 CTY	04 STATI	E 05 ZIP CODE	00 COUN			CODE	DIST
Avon	MA	02322	Norf	olk			<u> </u>
COORDINATES LATITUDE LONGITUDE			,				
Accountaines Dillions		•			-		
42 <u>07' 46".</u> <u>71° 03' 30'</u>	· <u> </u>				<u>.</u>		٠.
Take rt. 24 south to Harrison Blvd eas	st exit.	Left on (01d Pc	ond St.	Bodwel	il St.	is '
III. RESPONSIBLE PARTIES							
OT OWNER (F Enough)		ET (Business, made)					
Mr. Peter Runton	İ	491 Main		·	<u> </u>		
	04 STAT	E 05 ZIP COOE.	06	TELEPHONE NU	MBER"	•	
OS CITY	MA	02322	[40	08 ⁾ 580–1	108		•
Avon		ET (Burness, man	<u> </u>				
07 OPERATOR of known and officered from owner!							
same		- 1 1 1 mm c-4h-c	112	TELEPHONE NU	MBER.		
ON CITY	[10 STAT	E 11:20P CODE)	. ==		
•	· 1	<u> </u>	<u></u>		<u> </u>		
I A. RCRA 3001 DATE RECEIVED: (Specify)	CONTROLLED WAS		NKNOWN 	TE RECEIVED:			C. NONE
OLONGTE INSPECTION OLONGT INSPECTION OLONGTE INSPECTION OLONGT INSPECTION OL	DB. EPA CONTACTH OFFICIAL NAME(S): Gale S OF OPERATION 1972 ***COMMAND **TOTAL	RACTOR D F. OTHER: ASSOC.	8 Sc	hool St.	, Weym	confluction to the confluction of the confluction o	MA.
OF CHARACTERIZATION OF POTENTIAL HAZARD OF CHARACTERIZATION OF POTENTIAL HAZARD OF CHARACTERIZATION OF POTENTIAL HAZARD TO ENVIRONMENT AND/OR POPUL The Brockton Reservoir lies 1.1 miles a drinking water source. However, if purposes is being discussed.	DB.EPACONT ALTHOFFICIAL NAME(S): Gale RESOF OPERATION 1972 RECEIVED TO COMPOUNT ATION S. to the so Tuture use	PACTOR FOTHER: ASSOC. 1 TEM B ods, greated of this	8 Sc 989 Secretarians ase &	oil foundate. At body fo	Weymunknow	contractor to the contractor t	MA g fiel
OLONGITE INSPECTION F POTENTIAL HAZARD TO ENVIRONMENT AND OR POPUL The Brockton Reservoir lies 1.1 miles a drinking water source. However, if purposes is being discussed. V. PRIORITY ASSESSMENT OLONGITY ASSESSMENT OLONGITY ASSESSMENT OLONGITY FOR INSPECTION (Concernment Inspection Insp	DB.EPACONT ALTHOFFICIAL NAME(S): Gale SOF OPERATION 1972 SECTION ATTON S. to the sof	PACTOR FOTHER: ASSOC. 1 TEAM BANGER Outh of to this	8 Sc 989 Secretarians & Secretarians & Secretaria	oil foundate. At body fo	Weymunknown d in 1	eachin	g fiel
OLONSTE INSPECTION CONTRACTORN OLONSTE STATUS (Chical devi) OLONSTE STATUS (Chical devi) OLONSTE STATUS (Chical devi) OLONSTE INSPECTION OF POTENTIAL HAZARD TO ENVERONMENT AND/OR POPUL The Brockton Reservoir lies 1.1 miles a drinking water source. However, f purposes is being discussed. V. PRIORITY ASSESSMENT OLONSTE INSPECTION (Chical devi) August of mandation is chical of companient and/or popul OLONSTE INSPECTION (Chical devi) August of mandation is chical of companient and/or popul OLONSTE INSPECTION (Chical devi) August of mandation is chical of companient and/or popul OLONSTE INSPECTION (Chical devi) August of mandation is chical of companient and/or popul OLONSTE INSPECTION (Chical devi) August of mandation is chical of companient and/or popul OLONSTE INSPECTION (Chical devi) August of mandation is chical of companient and/or popul OLONSTE INSPECTION (Chical devi) August of mandation is chical of chical device in the c	DB.EPACONT ALTHOFFICIAL NAME(S): Gale SOF OPERATION 1972 SECTION ATTON S. to the SC Tuture use	PACTOR FOTHER: ASSOC. 1 TEAM BANGER Outh of to this	8 Sc 989 Secretarians & Secretarians & Secretaria	oil found	Weymunknown d in 1	eachin	g fieldis not
OI CHARACTERIZATION OF POTENTIAL HAZARD OI CHARACTERIZATION OF POTENTIAL HAZARD OI CHARACTERIZATION OF POTENTIAL HAZARD OZ STE STATUS (Character) OZ STE	DB. EPA CONTACT ALTH OFFICIAL NAME(S): Gale SOF OPERATION 1972 SECREPTION ATTON S. to the SOF THE SOF OPERATION S. to the SOF THE SOF OPERATION THE SOF OPERA	PACTOR FOTHER: ASSOC. 1 TEAM BANGER Outh of to this	8 Sc 989 Secretarians & Secretarians & Secretaria	oil found	Weymunknown d in 1	eachin	g fiel
OI CHARACTERIZATION OF POTENTIAL HAZARD OI CHARACTERIZATION OF POTENTIAL HAZARD OI CHARACTERIZATION OF POTENTIAL HAZARD OZ STE STATUS (Character) OA ACTIVE B. MACTIVE C. UNKNOWN CAN DESCRIPTION OF SUBSTANCES POSSBLY PRESENT, KNOWN OR ALLES Trichloroethylene detected in groundw Chlorinated solvents, volatile aromate OS DESCRIPTION OF POTENTIAL HAZARD TO ENVIRONMENT AND/OR POPUL The Brockton Reservoir lies 1.1 miles a drinking water source. However, f purposes is being discussed. V. PRIORITY ASSESSMENT OI PRIORITY FOR INSPECTION (Character) And Company (Character) VI. INFORMATION AVAILABLE FROM OI CONTACT Winifred Donnelly DED OT CONTACT Winifred Donnelly DED OT CONTACT DED	DB. EPA CONTALTH OFFICIAL NAME(S): Gale RS OF OPERATION 1972 RECEDENCY ATTON S. to the SC STUTUTE USE LOW (Proport on America) P.	PRACTOR F.OTHER: ASSOC. 1 TEM B Outh of this of this	8 Sc. 989 989 see &	oil found	D. OTHERO Weym UNKNOW d in 1	eaching withing within the withing withing withing withing withing withing withing win	g field is not ater 5
OI ON SITE INSPECTION OI ON SITE INSPECTION OF YES DATE ON OF SITE STATUS (CONSIDERATE) OI ON SITE STATUS (CONSIDERATE) OI ON SITE STATUS (CONSIDERATE) OI ON OF SITE STATUS (CONSIDERATE) OI ON SITE STATUS (CONSIDERATE) OI O	DB. EPA CONTALTH OFFICIAL NAME(S): Gale RS OF OPERATION 1972 RECEDENCY ATTON S. to the SC STUTUTE USE LOW (Proport on America) P.	PACTOR FOTHER: ASSOC. 1 TEAM BANGER Outh of to this	8 Sc. 989 989 see &	oil found	D. OTHERO Weym UNKNOW d in 1	eaching w	g fieldis not

CERCLIS DATABASE FORM

			BATE: 0730790
SITE NAME: VERCLIS No. MY	Winchester Indust	ries 85378670 PROJECT MANAGER:	
DIRECTIONS TO	SITE: take route Pond St. Bodwel	24 south to Harrison B 1 St. is the second le	oulevard east exit
ELEMENT	CERCLIS CODE (No. of positions)	DESCRIPTION	ÈNTRY
I. FOR ALL PROJE	ECTS		•
State MA	C2(2)	Postalicode	02322
Site iD (If available)	C101(12)	Dun & Bradstreet	
Site Name	C104(40)		<u>Winchester Industries</u>
Street Address	C110(25)		230 Bodwell St.
City	C111(25)	•	Avon, MA
County	*TBD		Norfolk
Ownership	C136(2)	FF = Federally ST = State ow CO = County of DI = District of IL = Indian la MI = Mixed or UN = Unknow *TBD = Municipal *TBD = Privately OH = Other	ned pwned pwned inds wnership rn ally owned
Years of operation	on: *TBD	1972 to 19 99	
FMS Number (if assigned)	· C315(4)	

ELEMENT 7	(No. of positions)	DESCRIPTION ENTRY
Recommendation of Most Recent Project at Site	C2103(1)	For PAS: H = High = SSI Required M = Med. = SSI Recommended N = NFRAP = No Further Remedial Acti
	7	Pianned
		For ŠŠis:
		R = Recommended for an LSI
	;	D = Deferred to another authority
	·	N = NFRAP = No Further Remedial Action Planned
•		For LSis:
	· · · · · · · · · · · · · · · · · · ·	G = Recommended for an HRS Scoring
•		N = NFRAP = No Further Remedial
		. Action Planned
· ——- ·		<u>M</u>
Note	过105(20)	Abbreviated Comments
		transce an estimate of the restrict.
Reasonsifor	er man en	•
Ineligibility (for		<u></u>
Sites Determined Ineligible under		
CERCLA)	*TBD	*TBD = Petroleum contamination only *TBD = Active RCRA facility
		*TBD = Properly applied pesticide
		*TBD = Nuclear/radioactive waste
		TBD = All other reasons
-1		
Agenty Responsible		T _ ITDA E Simmerod
for Work at Site	C2147(2)	F = EPA, Fund financed (S) = State, Fund financed
:		SN = State, no fund financing
T		FF = Federal facility
	•	*TBD = Responsible Party S
		
•		-

The second secon

ELEMENT	CERCLISICODE : (Na. of positions)	DESC.	RIPTION	ENTRY	
II. ONLY FOR SITE	WITH HRS				
Coordinates	*aeò	Latit	ude and Lon	gitude	42° 07' Lat. 71° 03' Long
Type of Facility of	<i>j</i>			•	
Source	C137(1)	, <u>B</u> , C	•	cal Plant ontamination II	
٠.		<u>M</u> N	= Manuf = Militar	acturing Plant ry Facility Federal Facility	•
		- Т Р А	= mines/ = Lagoo	tailings	nping:
if unknown, Type of Waste	* .				
Présent		R J *TBD	= inorga = Organ	active Waste inic Waste ic Waste	
• •			= Otner =Dioxir	Industrial Waste	•
If unknown, Type of Receptor Affected		, V	≕ Water	ways/river	
· · ;		.H .W. *TBD O	= Drinki	ng Area ng Water Wells gical Receptors TBD	
Abstract Site is locat	C201(240) ed in a commercia		Description town. To	richloroethylen	e was detected
in groundwate	•		• ,		nds, grease and
oil found in	leaching field.			· 	
		· · · · · ·		<u></u>	<u> </u>
		·		<u> </u>	

Site Name: CERCLIS No.: TDD No.: Reference No.:

MPL ELIGIBILITY CHECKLIST

		YES	<u>NO</u>	COMMENTS
	Are the wastes onsite considered hazardous, as defined in CERCLA?	X		
	*Sites covered by other authorities:	٠	•	
	Are the hazardous materials at the site sole petroleum products (gasoline, oil, natural gas)?	ly .	<u>X.</u>	
:	Is the contamination at the site caused solely by pesticides that were applied using an accepted practice?		<u>×</u> _	
	If the release is into public or private drinking water systems, is it due to deterioration of the system through ordinary use?		<u>×</u> .	
	Is the release from products which are part of the structure, and result in exposure within residential, business, or community structures?			
	Did the release result in exposure to people solely within a work place?		7	·
	Does the facility have an Underground Injection Control permit under the Safe Drinking Water Act?		<u>×</u>	
	Is the release the result of the normal application of fertilizer?		<u>×</u>	.
	Does the release involve naturally occurring substances in their unaltered form?		<u></u> Σ_	
	Does the contamination at the site consist solely of radioactive materials generated by Department of Energy/Atomic Energy Commission activities?		<u>-X</u>	
	Is the contamination at the site caused solely by coal mining operations?		<u>X</u>	
:	Does the facility have a permit from EPA or the U.S. Army Corps of Engineers (under the Marine Protection, Research, and	•		
	Sanctuaries Act) to dispose of dredged materials in ocean waters?		<u> </u>	

TOD No.: Reference No.:

	<u></u>	<u> </u>	COMMENTS
*Other issues of site definition:			•
Is the site defined solely as a contaminated well field?		X _	
Is the site currently owned or operated by a federal agency, or has it been in the past?	. `	X	
Is the site a municipal landfill?		X	
Check if there is documentation of industrial waste disposed of.	-		•
Does the waste consist of a "special waste" such as fly ash?		\angle	
Check if there is documentation of a hazardous component to the waste.		-	
Does the facility have an NPDES permit?		χ	
Check if the facility has a history of permit violations.			
Is the facility subject to ambient air quality standards under the Clean Air Act?		<u>X</u>	
Does the facility have a permit under the Clean Air Act?		Х.	
*RCRA status			
Has the facility notified as a RCRA generator?	X		
Has the facility ever had RCRA interim status or a RCRA permit?	*	X	
If yes, check any that apply:	٠.	,	
X The facility is a small quantity generator.			*
The facility is a "non-notifier" or "protective filer" (identified as such by EPA or the state).		· - .	·

te Name: RCLIS No.: TOD No.: Reference No.:

*RCRA status (continued)

- -- The owner of the facility is bankrupt, or the owner has filed for protection under bankruptcy laws (if known).
- A RCAA compliance order or notice of violation has been issued for the facility at some time.


The order or notice concerned: - conditions that posed a hazard (i.e. a release of contamination to the environment) OR

- administrative violations (i.e. recordkeeping or financial requirements).
- Some RCRA enforcement action is currently pending at the facility.
- · A RCRA permit has been denied or interim status has been revoked for the facility.

The permit or interim status was revoked:

- -because of conditions at the facility that posed a hazard OR
- -because the facility failed to meet an administrative requirement (i.e., failed to file an acceptable Part B permit application).
- A closure plan has been requested or submitted for the facility under RCRA.
- ---- A closure plan has been approved for
- A closure plan has been approved for the facility under RCRA.

 The facility is closed and currently monitoring under RCRA regulations.



BOOMERS INDUSTRIAL CATERERS

LEGEND

B-1 - BORING LOCATION & NO.

OC.B. - CATCH BASIN

- - SITE BOUNDARY

LF-1S O - LEACHING FIELD HOLDING TANKS

GROSSMAN CAP CO., INC.

BODWEL

QUALITY


ROADWAY EXPRESS.


Kurz Associates, Inc.

MAY 3, 1988

DRAWN BY: R.N.C.

P





SITE PLOT PLAN
WINCHESTER INDUSTRIES, INC.
230 BODWELL STREET
AVON, MASSACHUSETTS

NO: 1333

FIGURE 2